

Lanpro Auto Care Centre Ltd.

"Ultimate Service So You Can Have Safe and Breakdown Free Driving"

1870 Ellice Ave.

Winnipeg, MB, Canada R3H 0B9

Phone: (204) 783-5802 ~ Fax: (204) 783-9819

Email: lanpro@mymts.net ~ Website: www.lanproauto.com

GST#123610925RP0001

Authorization

Bill To Lanpro Repair Report
1870 Ellice Ave.
Winnipeg, MB R3H 0B9
Canada

Home
Email

Work Order # 76951
Service Advisor Lance Reinheimer
Technician Scott (5) A Reinheimer

Plate MB UCD868
Description White 2018 Hyundai Santa Fe Sport Premium L
2.4L 2359CC VIN B
VIN 5XYZUDLB2JG517621
Unit awd
Odometer 0 In / 236,964 Out

Appointment 2/25/2022 2:23 PM
Promised 3/31/2022 5:00 PM

Concern

Driveability Concern

"Check reason runs rough. Also, no start - dead key." Road test - scan for codes (p0301) and test components - advise: would start once doors locked and unlocked a few times (security malfunction due to dead battery). Check further - misfire on cylinder #1 - swapped coils and plugs - problem remained same - perform compression test - #1 cylinder was 20psi - others 150 psi - perform leak-down test - engine smokes and rattles - suggest engine

Labor			\$133.00 GP
Technician: Scott (5) A Reinheimer			
5W20 - ENGINE OIL	2 Litre	\$3.59 / Litre	\$7.18 GP
		Sub	\$140.18

Inspection

Used Vehicle Inspection

Labor			\$0.00 GP
Technician: Scott (5) A Reinheimer			
		Sub	\$0.00

Service

Clean and Polish

as necessary. Remove any dealer stickers. Steam clean underhood and engine. Headlight restore if necessary. Touch up paint as required

Labor			\$452.00 GP
Technician: (Alex) (9) Quang Duc Bui			
		Sub	\$452.00

Used Vehicle and Provincial Safety Inspection

Includes road test up to 90 kph, Prepurchase inspection, Lube oil and filter, Steam clean under carriage area, Check if has block heater and test. Lube door hinges.

5W20 - ENGINE OIL	5.5 Litre	\$3.59 / Litre	\$19.74 GP
8-51334 - Engine Oil Filter	1 Unit	\$8.60 / Unit	\$8.60 GP
Labor			\$212.80 GP
Technician: Scott (5) A Reinheimer			
		Sub	\$241.14

Factory Recalls

None at this time

Towing - Dr Hook Towing

Tow Charge	1 Unit	\$153.33 / Unit	\$153.33 GP
		Sub	\$153.33

Lanpro Auto Care Centre Ltd.

"Ultimate Service So You Can Have Safe and Breakdown Free Driving"

1870 Ellice Ave.

Winnipeg, MB, Canada R3H 0B9

Phone: (204) 783-5802 ~ Fax: (204) 783-9819

Email: lanpro@mymts.net ~ Website: www.lanproauto.com

GST#123610925RP0001

Used Engine Assembly (60,000kms) & Block Heater

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$1,556.10 GP
Technician: Scott (5) A Reinheimer			
013AM-00001 - Block Heater - OEM*	1 Unit	\$113.64 / Unit	\$113.64 GP
\$NW316-902 - Engine Assembly - 60,000kms	1 Unit	\$4,866.67 / Unit	\$4,866.67 GP
		Sub	\$6,536.41

Airbag Light Evaluation & RF Seat

Scan for codes (P1490) - check weight detection wiring - remove seat to check for wiring - will need seat assembly with sensor

Labor - test & inspect			\$143.00 GP
Technician: Scott (5) A Reinheimer			
Labor - replace seat			\$79.80 GP
Technician: Scott (5) A Reinheimer			
\$Y03909-950 - RF Seat - charcoal/cloth/manual	1 Unit	\$291.67 / Unit	\$291.67 GP
		Sub	\$514.47

Rear Wiper Blade

Labour			\$8.95 GP
Technician: Scott (5) A Reinheimer			
RT12 - Windshield Wiper Blade	1 Unit	\$17.69 / Unit	\$17.69 GP
		Sub	\$26.64

Install & Balance 4 Boto 104H SASQUA H/T SUV A/S Tires

235/65/17

Labour			\$119.80 GP
Technician: Scott (5) A Reinheimer			
B583675 - Boto 104H SASQUA H/T SUV A/S	4 Unit	\$212.63 / Unit	\$850.52 GPT
		Sub	\$970.32

Both Lower Ball Joints

Perform final road test where applicable.

Labor			\$79.80 GP
Technician: Scott (5) A Reinheimer			
K500231 - Lower Ball Joint	2 Unit	\$120.89 / Unit	\$241.78 GP
		Sub	\$321.58

4 Wheel Alignment

Labour			\$126.95 GP
Technician: Scott (5) A Reinheimer			
		Sub	\$126.95

LF Wheel Bearing and Hub Assembly

Labor			\$133.00 GP
Technician: Scott (5) A Reinheimer			
BR930946 - LF Wheel Bearing /Hub Assembly	1 Unit	\$294.89 / Unit	\$294.89 GP
		Sub	\$427.89

Centre Seat Belt Buckle

Labor			\$79.80 GP
Technician: Scott (5) A Reinheimer			
210 HY1418 1U - Centre seat belt buckle	1 Unit	\$125.00 / Unit	\$125.00 GP
		Sub	\$204.80

Lanpro Auto Care Centre Ltd.

"Ultimate Service So You Can Have Safe and Breakdown Free Driving"

1870 Ellice Ave.

Winnipeg, MB, Canada R3H 0B9

Phone: (204) 783-5802 ~ Fax: (204) 783-9819

Email: lanpro@mymts.net ~ Website: www.lanproauto.com

GST#123610925RP0001

(Front) Disc Brake Service - sliders seized

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labour			\$79.80 GP
Technician: Scott (5) A Reinheimer			
H-18223A - Disc Brake Hardware Kit	1 Unit	\$40.00 / Unit	\$40.00 GP
		Sub	\$119.80

(Rear) Disc Brake Service- sliders seized

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labour			\$79.80 GP
Technician: Scott (5) A Reinheimer			
		Sub	\$79.80

RR Wheel Well Liner & Re-Attach LR

Labor			\$133.00 GP
Technician: Scott (5) A Reinheimer			
86822-4Z000 - RR Wheel Well Liner - OEM*	1 Unit	\$162.31 / Unit	\$162.31 GP
		Sub	\$295.31

Sublet - Windshield

FW3885 - Windshield	1 Unit	\$526.67 / Unit	\$526.67 GP
		Sub	\$526.67

Total Parts	\$7,566.36
Total Labor	\$3,417.60
Total Sublet	\$153.33
Total Before Taxes & Miscellaneous Charges	\$11,137.29
(G) Canadian Goods and Services Tax (GST)*	\$0.00
Exemption #: On File	
(G1) GST on TDC*	\$0.00
(P) Manitoba Provincial Sales Tax (PST)*	\$0.00
Exemption #: On File	
(T) Tire Disposal Charge*	\$0.00 G1P
Grand Total	\$11,137.29

Wholegoods - UCD868 - 2018 Hyundai Santa Fe Sport Premium 4 Door White AWD 4 Cylinder Automatic

I hereby authorize the above work to be completed.

Customer Signature: _____